


TWR	GND	De-icing
118.600	121.800	127.025
118.850	118.125	133.850



**NOTE 1**  
Reduced wing tip clearances exist between aircraft on parallel taxiways / taxilanes as well as between aircraft and objects including parked aircraft and vehicles on service roads. On straight sections adhere strictly to the taxiway centre line markings, on curves follow manoeuvring methods - cockpit over centre line or judgmental oversteering.

**NOTE 2**  
In case of malfunction in the docking guidance system contact Helsinki Apron 121.650 MHZ.

**HOT SPOT 1, 2**  
FREQ change before crossing runway. An explicit crossing clearance shall be received before proceeding over the runway.

**HOT SPOT 3**  
Wide APN. Make sure of correct turn before runway when taxiing to RWY 04R.

CHG: TWY AJ, AV, VJ CL LGT, APN 1W ACFT stands CL LGT; APN 1W PAX bridges, ADDN Intermediate HLDG PSN TWY AV.

Docking guidance system for ACFT stands, see EFHK AD 2.9  
APN and ACFT stands details, see page EFHK AD 2.15 - 7  
TWY details, see page EFHK AD 2.15 - 11

**LEGEND**

- 30 — ACFT stands and TWY CL or lead-in line
- TWY and APN edge LGT
- TWY CL LGT
- APN spot
- Communication border

