

AIP SUPPLEMENT - SUOMI / FINLAND

Aeronautical Information Service

www.ais.fi

ANS Finland, PL 157, FI-01531 VANTAA, ais@ansfinland.fi

AIP SUP NR

42 / 2019

**WEF
25 APR 2019**

| | | | | |
|--|---|---|----------------------|-----------------------------------|
| Aihe | FINLAND FIR, TILAPÄINEN VAARA-ALUE EFD541 VAASA | | | |
| Subject | FINLAND FIR, TEMPORARY DANGER AREA EFD541 VAASA | | | |
| Voimassaolo Validity | 25 APR 2019 0300 UTC - 23 APR 2020 2100 UTC | | | |
| Aktivointi Activation | WILL BE ACTIVATED BY NOTAM | | | |
| Liikenne- ja viestintäviraston päätös Decision of Finnish Transport and Communications Agency | TRAFICOM/4180/05.00.12.00/2019, 8.4.2019 | | | |
| AIP REF | ENR 5.1 | Julkaisupäivä Publication date | 11 APR 2019 | |
| Alue / Area | | | | |
| | Designation Lateral limits | Vertical limits | Activity type | Remarks |
| | EFD541 VAASA 631625N 0215404E - 625405N 0220845E - 624947N 0213726E - 631204N 0212223E - 631625N 0215404E | <u>FL 195</u> SFC | PARACHUTE | AMC Manageable Area RMZ TMZ |
| ATS-palvelua antavat yksiköt / Units providing ATS service | | | | |
| | Unit | FREQ MHZ | OPR HR | Remarks |
| | ACC EFIN | 127.100 | H24 | |
| | APP EFVA | 125.850 | HO | |
| | TWR EFVA | 120.950 | NOTAM | |
| Huomioitavaa | Vaara-alue on mahdollista aktivoida vain EFVA TWR:n kiinnioloaikana ja vain laskuvarjohypytoimintaa varten. Vaara-alueen ollessa aktiivinen laskuvarjohypytoiminnalla tulee olla nimetty hyppyvalvoja, jonka on oltava jatkuvasti tavoitettavissa puhelimitse toiminnan aikana. Kyseisen henkilön puhelinnumero julkaistaan alueen aktivoivassa NOTAM:ssa. Aktivoitulla vaara-alueella olevien ilma-alusten tulee olla kuuntelulla FREQ 120.950 MHZ (EFVA TWR). NOTAM aktivointia 7 vrk ennen toiminnan aloittamista (ICAO vaatimus) ei voida taata. Tämä AIP SUP julkaisu sisältää xml-siirtotiedoston AIXM 5.1 muodossa julkaistujen alueiden sivu- ja korkeusrajoista. | | | |
| Remarks | The danger area can only be activated when EFVA TWR is closed and only for parachute activity. When the danger area is active it is mandatory to name a supervisor who can be reached by phone at all times during the activity. The phone number of the supervisor is published in the NOTAM that activates the danger area. Aircraft in the activated danger area must monitor FREQ 120.950 MHZ (EFVA TWR). ICAO 7-days advance notice (NOTAM) cannot be guaranteed. This electronic AIP SUP publication contains xml-file attachment in AIXM 5.1 format. | | | |

TEMPORARY DANGER AREA EFD541 VAASA

