

# AIP SUPPLEMENT - SUOMI / FINLAND

Aeronautical Information Service

www.ais.fi

ANS Finland, PL 157, FI-01531 VANTAA, ais@ansfinland.fi

AIP SUP NR  
**52 / 2019**

**AIRAC**

**WEF**  
**25 APR 2019**

## HELSINKI-VANTAA LENTOASEMA, RADIOYHTEYDEN KATKEAMINEN (RCF)

Julkaisupäivä 25.4.2019

REF AIP:

EFHK AD 2.22.2.12

RNAV STAR RWY 04L 1/2 (EFHK AD 2.12 - 1/2)

RNAV STAR RWY 04L 2/2 (EFHK AD 2.12 - 3/4)

RNAV STAR RWY 04R (EFHK AD 2.12 - 5/6)

RNAV STAR RWY 15 (EFHK AD 2.12 - 7/8)

RNAV STAR RWY 22L (EFHK AD 2.12 - 9/10)

RNAV STAR RWY 22R 1/2 (EFHK AD 2.12 - 11/12)

RNAV STAR RWY 22R 2/2 (EFHK AD 2.12 - 13/14)

RNAV STAR RWY 33 (EFHK AD 2.12 - 15/16)

Alla oleva menetelmä radioyhteyden katkeamisesta korvaa tekstisivulla ja kartoilla olevan RCF-menetelmän ja se otetaan käyttöön Helsinki-Vantaan lentoasemalla **25.4.2019** alkaen. Tiedot päivitetään AIP:hen karttojen seuraavan päivityksen yhteydessä.

Valitse transponderikoodi 7600.

Selvitys RNAV STAR:iin on saatu ja kuitattu:

Seuraa STAR:ia sen viimeiselle pisteelle saakka ja jatka lentoa viimeksi saadun ja kuitatun kiitotien IAF:lle. Jos vektoroitu, jatka lentoa kahden minuutin ajan viimeksi selvitettyllä ja kuitatulla ohjaussuunnalla ja korkeudella, hakeudu sitten STAR:n viimeiselle pisteelle ja jatka lentoa viimeksi saadun ja kuitatun kiitotien IAF:lle.

Selvitystä RNAV STAR:iin ei ole saatu ja kuitattu:

Jatka lentoa kahden minuutin ajan viimeksi selvitettyllä ja kuitatulla ohjaussuunnalla ja korkeudella, ja hakeudu viimeksi saadun ja kuitatun kiitotien IAF:lle.

IAF:lta suorita mittarilähestymismenetelmä kuitatulle kiitotielle ja vapauta kiitotie.

Ilma-aluksissa, joissa on puhelin, soittavat numeroon +358 9 6151 3324.

## HELSINKI-VANTAA AERODROME, RADIO COMMUNICATION FAILURE (RCF)

Publication date 25 APR 2019

REF AIP:

EFHK AD 2.22.2.12

RNAV STAR RWY 04L 1/2 (EFHK AD 2.12 - 1/2)

RNAV STAR RWY 04L 2/2 (EFHK AD 2.12 - 3/4)

RNAV STAR RWY 04R (EFHK AD 2.12 - 5/6)

RNAV STAR RWY 15 (EFHK AD 2.12 - 7/8)

RNAV STAR RWY 22L (EFHK AD 2.12 - 9/10)

RNAV STAR RWY 22R 1/2 (EFHK AD 2.12 - 11/12)

RNAV STAR RWY 22R 2/2 (EFHK AD 2.12 - 13/14)

RNAV STAR RWY 33 (EFHK AD 2.12 - 15/16)

Radio communication failure procedure as described below replaces the RCF procedure on the text page and on the charts and it will be introduced at Helsinki-Vantaa aerodrome on **24 APR 2019**. The procedure will be published in AIP on the next update of charts.

Select transponder code 7600.

RNAV STAR has been given and acknowledged:

Follow the STAR until the last waypoint and proceed to IAF of the last given and acknowledged RWY. If radar vectored, continue 2 minutes on last assigned and acknowledged HDG and ALT/FL, then resume STAR until the last waypoint and proceed to IAF of the last given and acknowledged RWY.

RNAV STAR has not been given and acknowledged:

Continue 2 minutes on last assigned and acknowledged HDG and ALT/FL, then proceed to IAF of the last given and acknowledged RWY.

From IAF execute IAP to the acknowledged RWY and vacate.

Aircraft having telephone, call +358 9 6151 3324.